

Office: Executive Engineer, Construction Division No. 2 PWD B&R Br.,
Bathinda

Phone No.: 0164-2212428

email: - xenc2bti@gmail.com

No. - 1513

Dated - 02/06/2026

To

The Principal
Sudesh Vatika Convent Sen. Sec. School
V.P.O. Bhagiwander, Distt. Bathinda


Subject: Issuance of Building Safety Certificate for the Year 2026-27

Reference: Your letter dated 01.06.2026.

With reference to the subject cited above and your letter mentioned under reference, your application for obtaining the Building Safety Certificate for the school building for the year 2026-27 was received in this office. The school building was visually inspected by the office of the Sub-Divisional Engineer. Based on their report/recommendations, the School Building Safety Certificate for the year 2026-27 is hereby issued and shall remain valid up to **31.03.2027** subject to the following observations and conditions:

1. The school must have a plan to deal with any emergency or unforeseen incident, including the safe evacuation of children from the building and coordination with the concerned departments during emergencies. The school should regularly review and update this plan to ensure its effectiveness.
2. If any addition, alteration, extension, modification, or renovation is required or carried out in the building, immediate inspection by this office should be arranged. After completion of such work, a fresh safety certificate for the concerned portion must be obtained from this office.
3. If the walls, foundations, or roofs of the building settle, weaken, or sustain damage due to natural disasters or any other reason, the school shall immediately inform this office about the condition of the building. The building shall only be put into use after inspection and approval.
4. Separate Fire Safety Certificate and Electrical Safety Certificate must be obtained from the concerned departments.
5. The responsibility for carrying out repairs to ensure the safety of the school building lies with the school management. Notwithstanding this report, the school management shall remain fully responsible for the building's safety in all respects.
6. You are directed to obtain the Structural Safety Certificate for the year 2026-27 to confirm the structural safety of the building during the said period.
7. Appropriate safety training should be provided to school staff members, including emergency first aid procedures and evacuation protocols.
8. As per the covered area of the school, an amount of **Rs. 10,000/- (Rupees Ten Thousand Only)** has been received as Building Inspection Fee through G.R. No. 1745284.
9. This report is **not valid for legal purposes**.

D/A Building certificate file


Executive Engineer
Const. Divin. No. 2, PWD B&R
Bathinda